Greater Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward

Street ID	Street Name	Significant Landmark
W0201, W0207, W0256, W0203, W0209, W0211, W0362, W	NA, Ambedkar Nagar Slum, Maheshwari Nagar Main Rd	Down Bazaar road near Nagareshwara temple

Segment No.	Total Length (m)
1/C-W0201/S093007	163.56

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	56.78	77.594521	13.101413	77.594733	13.101875	W0356	W0311
2	106.78	77.595419	13.102434	77.596369	13.102667	W0211	W0203

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Constructions of Drain at Down Bazaar road near Nagareshwara temple and Surrounding areas in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	2000000	2017

Year	Type of Work	Other Work Type
2017 - 2018	Others	CC DRAIN

Tender	Work Details	Job No. / Work Code
Tender	Constructions of Drain at Down Bazaar road near Nagareshwara temple and Surrounding areas in Ward no 01 of Yelahanka Sub-Division Yelahanka zone	001-17-000014

Work Order No.	Work Order Date	Period of Extention
EE (YNK.D)E-PMT-09/WO/56/2017-18	30/05/2017	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
26/06/2017	25/06/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SAMBASHIVA REDDY C		0.00

Phone No.	E-Mail ID

9972747359

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SACHIN
Date of Inspection	**Remarks**	
08/07/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0201, W0207, W0256, W0203,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/07/2017	07/08/2017	COMPLETED
SE	VASU K M	08/07/2017	07/08/2017	COMPLETED
EE	VASU K M	08/07/2017	07/08/2017	COMPLETED
AEE	DEVARAJ	08/07/2017	07/08/2017	COMPLETED
AE	SACHIN	08/07/2017	07/08/2017	COMPLETED
AE	SACHIN	08/07/2017	07/08/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0201, W0207, W0256, W0203,